TF-2 TOP AND FACE SHARPENER

OPERATOR'S MANUAL



MADE IN THE U.S.A.

RIGHT



Contents

LIMITED WARRANTY	2
COOLANT SAFETY	
GENERAL SAFETY RULES	
SPECIFICATIONS	
FEATURES	
OPTIONS	
COMMON REPLACEMENT PARTS	7
STANDARD ACCESSORIES	7
PRE SET UP COOLANT	8
MACHINE INSTALLATION	8
AIR SUPPLY	9
CONTROL PANEL	10
SETUP CHECKLIST	13
GRINDING HEIGHT ADJUSTMENTS	16
THINGS TO CHECK IF PROBLEMS EXIST	17
MAINTENANCE	
CENTRAL LUBRICATOR SYSTEM	19
GRIND SPEED	2 1
AIR SCHEMATIC	29
OUTPUT PANEL WIRING SCHEMATIC	33
POWER PANEL	
ELECTRICAL SCHEMATICS	40
PARTS LIST	
MOTOR REPLACEMENT INSTRUCTIONS	68
BELT REPLACEMENT INSTRUCTIONS	69
SPINDLE REPLACEMENT INSTRUCTIONS	70
INDEX	72



LIMITED WARRANTY

This machine is warranted against defects in workmanship and materials under normal use and proper maintenance, for three years after date of purchase or 3,000,000 tips, whichever comes first. Any part which is determined to be defective in material or workmanship and returned to WRIGHT MACHINE TOOL CO., shipping costs prepaid will be repaired or replaced, at WRIGHT MACHINE TOOL CO. option.

WRIGHT MACHINE TOOL CO., INC. 365 Palmer Avenue Cottage Grove, Oregon 97424

Phone (541) 942-3712 Fax (541) 942-0730





COOLANT SAFETY

Proper coolant maintenance will increase grinder life and grinding performance, and possibly reduce any risks associated with health concerns. Lack of proper coolant maintenance can result in increased exposure to grinding grit, bacteria, and other by products of grinding that may lead to increased skin sensitivity in some individuals.

WARNING!

Coolants used in this machine must be designed to be used in wet grinding operations. <u>Do not use automotive coolant.</u> Check with the manufacturer of the coolant to make sure it is designed for use in wet grinding of saws.

Water based coolants are designed to operate at precise mixture ratios. Check with the manufacturer of your coolant to determine the proper mix ratio.

CAUTION

Residual cleaning solutions on the saw will easily be dissolved into the coolant tank and can dramatically affect the chemistry of coolant which can significantly reduce wheel life, coolant efficiency, and corrosion efficiency.

Maintain the coolant filters that were shipped with this machine. If you have any questions on how to maintain the filters, call the factory at 1-541-942-3712

Test your coolant at regular intervals. Contact the manufacturer of your coolant to determine when to test, and which tests to perform.

Warning signs of improperly maintained coolant:

- 1. Strong (foul) odor coming from the coolant.
- 2. Color change in the coolant.
- 3. Noticeable stickiness on the saw.
- 4. Rust developing on the machine and/or saw steel.
- 5. Unexplained skin rash.
- 6. Deterioration of paint and/or plastic parts.

If you detect any of these warning signs consult the coolant manufacturer at once. If you are having trouble contacting the coolant manufacturer, call Wright Machine Tool Co. Inc. at 1-541-942-3712



GENERAL SAFETY RULES

Failure to follow the Safety Rules and other basic precautions, may result in serious injury.

Always use eye protection: When operating this machine, eye protection should be worn. Grinding particles and the possibility of wheel breakage make eye protection necessary. Also face or dust mask if operation is dusty. Use adequate ventilation.

Use ear protection: If operation is creating excessive noise.

Disconnect power: To machine when NOT in use.

Keep clear: Of grinding wheels and pinch points when machine is running.

Saws are sharp: Wear appropriate personal protective equipment when handling saw blades.

Mounting of wheels: Should only be done by persons with mechanical aptitude and good knowledge of mounting, care, and inspection of grinding wheels. Wheels must be rated for the RPM of the machine.

Dress properly: Do not wear loose clothing or jewelry. Nonskid foot wear is recommended. Wear protective hair covering to contain long hair.

Avoid dangerous environments: Don't use in wet location. Keep work area well lit. Do not use this machine in the presence of flammable liquid or gasses.

Keep children away: Do not let VISITORS contact this machine.

Keep work area clean: Cluttered areas invite accidents.

All electrical covers: Must be in place before applying electrical power to this machine. Electrical service must be locked out prior to removing any electrical covers or machine guards. Access to electrical components must be restricted to trained personnel only to avoid possible electrical shock.



GENERAL SAFETY RULES (CONTINUED)

Voltage greater: Than specified on name plate can result in serious injury to user.

Never stand on this machine: Serious injury could occur if the machine is tipped or if the grinding wheel is accidentally contacted.

Follow safety precautions: For wheels, coolant and material being ground. These items must also be compatible. This information is available on the Safety Data sheet for each of these products.

SPECIFICATIONS

Talon TF-2, an Automatic Top or Face Grinder Programmable for many tooth geometries.

FLATS: 1 Pass
ALTERNATES: 1 Pass
TRIPLE CHIP: 3 Passes

STANDARD VOLTAGE: 230 Volt, 3 Phase, 50/60 HZ OPTIONAL VOLTAGE: As Requested

SHIPPING WEIGHT: 2,200 lbs.

MACHINE WEIGHT: 1,900 lbs.

MACHINE SIZE: L 54" X W 35" X H 74"
AIR REQUIREMENTS: 2 C.F.M. at 80 psi to 100 psi

STANDARD SAW SIZE: 4" to 34"

SPINDLE MOTOR: (1) 2 h.p. 3450 RPM Motor

CIRCUIT SIZE: 230 VOLTS 15 A



FEATURES

The Wright Machine Tool "TALON TF-2" features massive construction with a weight of over 2,000 lbs. but uses only 15 square feet of floor space. Central lubrication system reduces maintenance requirements and increases machine life. The precision 2 horsepower grinding head moves on a robust double track multi-truck linear slide system powered by hydraulic controlled feed, giving high accuracy and productivity. The enclosed grind cabinet improves the work environment by containing noise and coolant.

The "TALON TF-2" features include:

- 10 G.P.M. Filtered Flood Coolant
- Totally Enclosed
- Low Voltage Work Lights
- Precision 2 H.P. Spindle Motor
- Dual Pressure Saw Clamp
- Precision Multi Bearing Spindles
- Auto Central Lubrication System
- External Pitch Adjustment
- Lift Off Grind
- External Plate Thickness Adjustment

Notice

TALON TF-2 series products and the information in this user guide are the proprietary property of Wright Machine Tool Co. Inc. or its licensors and may not be copied, disclosed, or used for any purpose not expressly authorized by the user thereof.

Wright Machine Tool Co. Inc. is constantly seeking ways to improve its entire product line of machinery, and therefor reserves the right to change this manual and hardware mentioned therein at any time without notice.

In no event will the provider of this equipment be liable for any incidental, consequential, or special damages of any kind or nature whatsoever, including but not limited to lost profits arising from or in any way connected with the use of the equipment or this user manual.

SAFETY FIRST!



OPTIONS

LARGE BORE OPTION
3 PIN SAW CENTER
W-450
SPLINE BORE SAW CENTER
W-460
SAW CENTER WASHER
FACE WHEEL
D-25
TOP WHEEL
D-37-6-2

COMMON REPLACEMENT PARTS

FINGER ARM PIVOT BEARING	W-188
RAMP FOLLOWER	W-1330
FEED FINGER	W-259-1
FINGER BOSS	W-287
FINGER SPRING	W-280
FINGER ARM SPRING	W-384-1
FILTER PAPER	A-5825
FIXED CLAMP JAW	W-1322-1
FEED RAMP	W-1324

STANDARD ACCESSORIES

1 - 1/4 TEE HANDLE KEY	A-5920
1 - 13 PC. ALLEN WRENCH SET	A-5923
8 - 5 Through 40° ALTERNATING ANGLE WASHERS	X-Z-04
9 - SAW BUSHING SIZES 1/2", 5/8", 3/4", 1", 1-1/8",	
30mm, 1-1/4", 1-3/8", 1-1/2".	X-Z-02
1 - MAGNETIC SAW RECEIVER 1/2" TO 1-1/2"	X-Z-03
2 - COOLANT FILTERS	A-5825
3 WHEEL DOSITION STORS	





PRE SET UP COOLANT

Coolant capacity is 15 gallons. A rust inhibiting grinding coolant **MUST** be used or severe rust damage to machine can result. Mix coolant according to manufacturer's instructions. COOLANT FILTERS - Clean coolant will increase grinding wheel life, improve grind finish and increase removal rates. Change coolant filter as necessary. Part # A-5825.

RUST DAMAGE IS NOT COVERED BY THE WARRANTY

MOUNTING GRINDING WHEELS

All grinding wheels must be rated for the RPM of this machine. Wheels exposed to higher than rated RPM are dangerous.

Mounting of the grinding wheel should only be done by persons with mechanical aptitude and good knowledge of mounting, care, and inspection of grinding wheels.


The TALON TF-2 can use 2 wheels. (D-36 for facing and D-37 for topping). Install the D-36 6" diameter facing wheel first with the diamond facing to the left. Then install the D-37 4-1/2" diameter topping wheel with the diamond facing to the right. With those 2 wheels back to back it will not be necessary to change when going from top to face. Individual face or topping wheels are also available.

Manufacturer recommends that separate 6" wheels be used for topping and facing. D-37-6-2 for topping. D-50 or D-51 for facing.

MACHINE INSTALLATION

Lifting this machine should only be done with a forks under the Machine base. Machine weight is approximately 1,900 pounds.

RECOMMENDED FLOOR SPACE FOR MACHINE AND OPERATOR



AIR SUPPLY

Your Talon TF-2 uses pneumatic and low voltage D.C. actuators to supply machine movements. These movements are superior to hydraulic controlled grinding machines.

Advantages of Pneumatic vs. Hydraulic...


- 1. Does not add vibration to Grinding machine which improve finish, speed and accuracy.
- 2. Does not build up heat which increases accuracy and eliminates a need for "warm up".
 - 3. No oil to dispose of.
 - 4. No oil leaks.
 - 5. Easy and inexpensive to repair.
 - 6. Safety.

Your Pneumatic system should give years of trouble free operation if the following rules are followed.

- 1. Air pressure must be above 80 psi at all times during operation.
- 2. Do not use a oiler in the air line.
- 3. Do not use synthetic oil for lubrication as it can attack the o-rings in the machine.
 - 4. The air should be reasonably dry and free of scale.
 - 5. The air line to the machine must be 3/8 ID hose or larger.



CONTROL PANEL







CONTROL PANEL (continued)

- **c-1. TOTALIZER:** The tooth totalizer will keep a tally of the total teeth ground.
- c-3. PROGRAM SELECTOR:
- **c-5. EMERGENCY STOP:** The panic stop is depressed if an emergency situation arises. Do not use this as a normal stop button.
- **c-6. START / STOP:** Pull to start / push to stop. If the joy switch is in auto when started the machine will index and then start it's grind cycle. If the joy switch is out of auto and the start button is pulled a second time the coolant will shut off. To restart the coolant pull the start button again or place the joy switch in to automatic.
- **c-7. TOOTH COUNTER:** The tooth counter is normally set for the number of teeth in the saw. To reset the counter during automatic operation, pull the start button and the counter will return to 0.
- **c-8. JOY SWITCH:** When the machine is not running the joy switch controls the saw movement. (IN) moves the saw up, (OUT) moves the saw down. To position the saw height, place the height sensor on the index finger and hold the joy switch to (IN), the saw will raise to position and lock. When the machine is running the joy switch controls manual index or feed or starts the automatic cycle. If you are unsure of the program, step the machine through the cycle 1 tooth at a time. Index/Feed, etc.

Note: The height sensor must be rotated out of the grind area and rested on the dowel pin when not in use.

- **c-9. HOOK:** angle switch operates at full speed (13 degrees per second) when the machine is off and at 1/2 degree per second when the machine is running. Hook angle can be jogged (with care) during the grind cycle.
- **c-10. INDEX PITCH:** To adjust the tooth pitch, pull the pitch adjustment knob out and turn to desired pitch length. Do not adjust while the machine is cycling.



CONTROL PANEL (continued)

c-11. PLATE THICKNESS: Turn the plate thickness full clockwise, this is 0 plate thickness position. Turn the plate thickness knob counter clockwise to the thickness of the plate being ground. Each turn equals .100.

c-12 / 13. FEED SPEED ADJUSTMENTS: Two speed knobs control the traverse speed forward and reverse. If lift off is in the yes position, feed reverse (the right knob) should be full open. The forward speed control is on the left. The normal range of grinding speed will be 1 to 3 turns open on forward speed.

c-14. ELECTRICAL DISCONNECT: The main power disconnects all power components in the machine. This should be used for extended time shutdown.

c-15. MONITOR LIGHT: The machine's monitor light will signal when the machine stops it's automatic cycle. The first minute down, the light blinks on for 1 second, off 3 seconds. At 2 minutes it flashes on for 1 second, off for 1 second. At 3 minutes it flashes on for 1 second, off for 1/3 second. At 4 minutes the monitor light stays on. To turn the monitor light off, restart the machine, or move the joy switch out of automatic. The machine monitor also reminds you when routine maintenance is needed. At 100,000 cycles the monitor light flashes on for 10 seconds off for 1 second. To reset after maintenance is completed, push the start / stop button in and hold the joy switch in the index position for 10 seconds.





SETUP CHECKLIST

- 1. Select the desired program
- 2. Set the number of teeth.
- 3. Set the hook / back angle.
- 4. Set the tooth pitch.
- 5. Set the plate thickness.
- 6. Set the forward speed 1 to 2 turns open.
- 7. Install the proper saw bushing.
- 8. Position the saw.
- 9. Install the wheel position stops.
- 10. Install the proper bevel angle washer, if bevels are being ground.
- 11. Close the door.
- 12. Pull start.
- 13. Move the joy switch to index, check index pitch adjustment.
- 14. Place in auto.
- 15. Grind the saw.

RELOAD CHECK LIST

- 1. Open door.
- 2. Remove saw.
- 3. Install next saw, close the door.
- 4. Pull start.





TALON TF-2 (SETUP)

NOTE: It is very important during the first day of operation to only grind alternate or straight saws. This will greatly reduce frustrations and speed up the learning process.

NOTE: If the air pressure to the machine drops below 75lbs. the machine will stop feed forward until the air pressure returns to required pressure of 90lbs.

- **1.** Select the desired grind program from the chart at the back of this manual. Set the grind program to that selection. If the machine is in face position and a Top Grind program is selected the machine will not feed forward.
- 2. Set the tooth counter c-7 to the number of teeth required.
- **3.** Place the joy switch c-8 in the center position.
- **4.** Set the Hook / Back angle by moving Hook angle switch c-9.
- **5.** Adjust the index pitch c-10.
- **6.** Determine the plate thickness and adjust c-11 as required. To remove back lash always be turning counter clockwise for final adjustment.
- 7. Adjust the feed speed c-12 to 1 turn open.
- **8.** Turn the electrical disconnect c-14 to **ON**.
- 9. Install the proper saw bushing and mount the saw.






Talon TF-2 (Setup continued)

- **10.** Place the height sensor on the index finger and hold the joy switch c-8 to IN. The saw will rise to position and lock. Rotate the height sensor out of the way resting on the coolant arm bracket. This locks to the height adjustment.
- **11.** Install the wheel position stop that matches the wheel and grind position. 6" top 6" face 4.5" top stops are adjustable and are located between head and base and above slide system.
- **12.** Install the proper bevel angle washer on 3/8 pin. See page 13 (h6)
- **13.** Position the correct tooth against the index finger. This is shown on the grind program chart diagram.
- **14.** Pull the **START / STOP** c-6 to start the machine.
- **15.** Move the joy switch c-8 to index until the index is full forward. If the index finger does not follow the radius of the saw adjust the index guide ramp as necessary with the 1/4 hex Tee handle.
- **16.** Move the joy switch c-8 to IN. This will move the grinding head forward. Adjust the infeed W-1 until proper removal is achieved. See page 13 for (h1).
- **17.** Finish grinding the set up tooth.
- **18.** Index to the next tooth.
- 19. Place joy switch IN to AUTOMATIC. The machine will complete the saw.



GRINDING HEIGHT ADJUSTMENTS



- **h-1.** Infeed moves grinding spindle (In-Feed) to compensate for wheel wear or wheel thickness.
- **h-2.** Adjust lift off stroke when face grinding.
- **h-5.** Indicator.
- **h-6.** Bevel angle adjustment. Zero through 40 degree washers are stored in the tool drawer.

THINGS TO CHECK IF PROBLEMS EXIST

MACHINE DOES NOT CYCLE.

1. Air pressure 90psi does not drop below 75psi at any time.

Pressure switch will stop cycle if air pressure is too low.

- 2. Are flow controls c-12, c-13 (page 7) open?
- 3. Stop blocks in place and adjusted.
- 4. Be sure index is working properly forward and reverse.
- 5. Check fuses on output panel.
- 6. Be sure feed forward and feed reverse proximity switches are tripping.
- 7. Be sure index proximity switch is tripping.

MACHINE DOES NOT RUN.

- 1. Machine plugged in?
- 2. Main disconnect on c-14, page 7.
- 3. Panic button.
- 4. Check overload on power panel inside side door.
- 5. Check fuses 10 amp in line and 8 amp on primary and secondary side of machine tool transformer check fuses on output panel.

MACHINE DOES NOT INDEX.

- 1. Check air pressure.
- 2. Stop block in place.
- 3. Check for hang up if not moving free with air disconnected.

SAW LIFT DOES NOT MOVE.

- 1. Be sure that sensor is in the proper position.
- 2. Be sure proximity switch is on while moving up or down.





The useful life of this machine can be dramatically extended if the following rules of operation are followed.

- 1. Clean the machine regularly to avoid carbide buildup in the enclosure.
- 2. Leave all inspection covers closed and in place. Only open inspection covers during maintenance.
- 3. A good rust inhibiting coolant must be used in the correct ratio. Too weak a mix will cause rust problems and too thick will damage the paint and load the Diamond wheels.
- 4. When not in use leave the enclosure door open. This eliminates humidity build up in the enclosure.
- 5. Do not clean the machine with high pressure air or water. This can blow grit into the internals of the machine and cause rusting problems which is not covered by warranty.

MAINTENANCE

DAILY 1. Check coolant level and filter.

2. Clean interior of machine.

3. Check oil level on central lube system.

WEEKLY 1. Check coolant tank for carbide buildup.

2. Replace coolant filters.

MONTHLY

1. Grease hook pivot.

or 100,000 CYCLES 2. |

2. Inspect finger for wear.

3. Inspect clamp jaws and ramp for wear.

EVERY 6 MONTHS or 500,000 CYCLES

1. Inspect spindle drive belt.

2. Clean spindle motor fan.

3. Remove stainless splash guards and clean completely.

4. Inspect and clean central lube points for lubrication, linear

slide system, bevel pivot, and spindle slide.

5. Inspect lube filter.

EVERY 24 MONTHS or 1,000,000 CYCLES

1. Replace spindle drive belt and inspect pulleys.

2. Inspect pulleys for wear.





CENTRAL LUBRICATOR SYSTEM C-6060

Description

This unit pumps once every fifteen minutes of operation. To manually lubricate pull knob up. Lubricator is located at the left end of the machine under the top cover.

Oil type Way Oil HD220

Expected Consumption Every three months

(250 hours of operation)

Filter part # A-6062

Inspect 6 months


Replace 12 months





<u>Discharge Volume Per Cycle:</u> Adjustable from 2.5cc minimum to 5.0cc maximum. The lubricator is supplied at the maximum stroke setting. To reduce oil deliver, remove the lock screw, measure **A**, turn adjusting screw clockwise, increasing dimension **A** in the increment (corresponding to the desired discharge) as shown on Table.

dim. "**A**" —



IN.	DISCHARGE		
.400	2.5cc		
.320	3.0cc		
.240	3.5cc		
.160	4.0cc		
.080	4.5cc		
0	5.0cc		

Filter Replacement: A filter at pump inlet protects the lubrication system and should be inspected every six months. If not clean, replace. To remove filter, pry out snap ring with screwdriver and remove filter discs and screens. To reinstall, insert in the following order: Filter disc support (coarse screen), filter disc screen (fine screen), filter disc, filter clamp ring and filter snap ring.

<u>Motor Replacement:</u> Remove motor cover and the motor mounting screws. To reassemble, be sure slot in motor shaft engages with pin in drive shaft before replacing screws. When ordering motor, see instructions included in drawing on front of sheet.

Maintenance: Check oil level daily and refill when required. Replace



GRIND SPEED TALON TF-2

* CYCLE TIME IN SEC. PER TIP	TEETH PER MINUTE	FEED RATE INCH PER MIN.DEI	**MAX. RECOMMENDED PTH OF CUT.180 GRIT WHEEL
0.4	00	47.0	202
2.1	29	17.2	.006
2.5	24	12.6	.020
2.9	21	9.9	.030
3.3	18	8.2	.036
3.7	16	7.0	.043
4.1	15	6.1	.049 +
5.0	12	4.7	.049 +
6.0	10	3.8	.049 +
8.0	7.5	2.4	.049 +

- * 10° ATB TOP 1-1/4 PITCH
 .315 TOTAL HEAD MOVEMENT
 3/16 DIAMOND SECTION
 10 GPM COOLANT FLOW
 OFF CARBIDE TIME IS 1.01 SEC.
- ** GRINDING WHEEL QUALITY,
 CONCENTRATION, AND BOND HARDNESS
 MAY REQUIRE REDUCED DEPTH OF CUT.





PROGRAM FLAT

This program is for flat top or flat face sharpening. No pre set heights are required.

- 1. Set grind program C-3 on control panel to Right/Flat or Left to change wheel rotation.
- 2. Set back angle (hook angle if face sharpening) at hook switch C-9 on control panel.
- 3. Set # of teeth to be sharpened on tooth counter. C-7 on control panel.
- 4. Install 0° washer located inside of tool drawer to the H-6 location.
- 5. Load saw. Use proper bushing located in tool drawer. Tool drawer is located under bottom row of adjustments, just under the control panel.
- 6. Use height sensor to set saw height. The height sensor arm is located above and behind the fixed clamp jaw. Rotate the arm so it is near the index finger. Then rotate the saw so the height sensor arm will rest on the tooth. Hold the joyswitch C-8 to in to move the saw up until the arm is lifted by the saw to the proper height (the saw lift will stop automatically). Now rotate the arm so it rests against pin behind height sensor arm. The saw is now at the proper height.
- 7. Pull start button C-6 on control panel. Note that the coolant can be toggled on/off with the start button, while putting the joyswitch into automatic will always turn the coolant on.
- 8. Set index pitch. This is done by holding the joyswitch C-8 to index, while turning knob C-10 to the desired setting. Make sure that C-10 locks into position before releasing C-8 to the center position. This process may need to be repeated to fine tune the index system.
- 9. Index the set up tooth into position.
- 10. Turn the spindle motor on by briefly jogging the joyswitch C-8 to the IN position. Adjust feed speed forward C-12 to desired speed. Use caution not to let the grinding wheel contact the carbide too hard. You can also adjust feed reverse C-13 at this time. Typically C-13 is adjusted fully open.
- 11. While adjusting feed speeds, the stroke length can also be set. When using a 6" top wheel select the 6" top stroke adjustment block. When using a 6" face wheel select the 6" face stroke adjustment block. When using wheel combination and a 4.5" top wheel select a 4.5" adjustment block. The stroke length can be adjusted by turning the knurled knobs on the selected block. This block is located between grind head and base and to the right of the hook scale.





PROGRAM FLAT (Continued)

- 12. Turn H1 infeed knob for desired carbide removal. The dial indicator H5 can be used to set the specific amount of material removal.
- 13. When the set up is complete, then select AUTO on joyswitch C-8.

PROGRAM LEFT

This program is used for left top, or left flat face sharpening.

- 1. Set grind program C-3 on control panel to Left.
- 2. Set back angle (hook angle if face sharpening) at hook switch C-9 on control panel.
- 3. Set # of teeth to be sharpened on tooth counter. C-7 on control panel.
- 4. Load saw. Use proper bushing located in tool drawer. Tool drawer is located under bottom row of adjustments, just under the control panel.
- 5. Use height sensor to set saw height. The height sensor arm is located above and behind the fixed clamp jaw. Rotate the arm so it is near the index finger. Then rotate the saw so the height sensor arm will rest on the tooth. Hold the joyswitch C-8 to in to move the saw up until the arm is lifted by the saw to the proper height (the saw lift will stop automatically). Now rotate the arm so it rests against pin behind height sensor arm. The saw is now at the proper height.
- 6. Install desired bevel angle washer onto H6. Washers are located in tool drawer.
- 7. Pull start button C-6 on control panel. Note that the coolant can be toggled on/off with the start button, while putting the joyswitch into automatic will always turn the coolant on.
- 8. Set index pitch. This is done by holding the joyswitch C-8 to index, while turning knob C-10 to the desired setting. Make sure that C-10 locks into position before releasing C-8 to the center position. This process may need to be repeated to fine tune the index system.
- 9. Index the set up tooth into position.
- 10. Turn the spindle motor on by briefly jogging the joyswitch C-8 to the IN position. Adjust feed speed forward C-12 to desired speed. Use caution not to let the grinding wheel contact the carbide too hard. You can also adjust feed reverse C-13 at this time. Typically C-13 is adjusted fully open.



PROGRAM LEFT (Continued)

- 11. While adjusting feed speeds, the stroke length can also be set. When using a 6" top wheel select the 6" top stroke adjustment block. When using a 6" face wheel select the 6" face stroke adjustment block. When using wheel combination and a 4.5" top wheel select a 4.5" adjustment block. The stroke length can be adjusted by turning the knurled knobs on the selected block. This block is located between grind head and base and to the right of the hook scale.
- 12. Turn H1 infeed knob for desired carbide removal. The dial indicator H5 can be used to set the specific amount of material removal.
- 13. When the set up is complete, then select AUTO on joyswitch C-8.

PROGRAM RIGHT

This program is used for right top, or right flat face sharpening.

- 1. Set grind program C-3 on control panel to Right.
- 2. Set back angle (hook angle if face sharpening) at hook switch C-9 on control panel.
- 3. Set # of teeth to be sharpened on tooth counter. C-7 on control panel.
- 4. Load saw. Use proper bushing located in tool drawer. Tool drawer is located under bottom row of adjustments, just under the control panel.
- 5. Use height sensor to set saw height. The height sensor arm is located above and behind the fixed clamp jaw. Rotate the arm so it is near the index finger. Then rotate the saw so the height sensor arm will rest on the tooth. Hold the joyswitch C-8 to in to move the saw up until the arm is lifted by the saw to the proper height (the saw lift will stop automatically). Now rotate the arm so it rests against pin behind height sensor arm. The saw is now at the proper height.
- 6. Install desired bevel angle washer onto H6. Washers are located in tool drawer.
- 7. Pull start button C-6 on control panel. Note that the coolant can be toggled on/off with the start button, while putting the joyswitch into automatic will always turn the coolant on.
- 8. Set index pitch. This is done by holding the joyswitch C-8 to index, while turning knob C-10 to the desired setting. Make sure that C-10 locks into position before releasing C-8 to the center position. This process may need to be repeated to fine tune the index system.



PROGRAM RIGHT (Continued)

- 9. Index the set up tooth into position.
- 10. Turn the spindle motor on by briefly jogging the joyswitch C-8 to the IN position. Adjust feed speed forward C-12 to desired speed. Use caution not to let the grinding wheel contact the carbide too hard. You can also adjust feed reverse C-13 at this time. Typically C-13 is adjusted fully open.
- 11. While adjusting feed speeds, the stroke length can also be set. When using a 6" top wheel select the 6" top stroke adjustment block. When using a 6" face wheel select the 6" face stroke adjustment block. When using wheel combination and a 4.5" top wheel select a 4.5" adjustment block. The stroke length can be adjusted by turning the knurled knobs on the selected block. This block is located between grind head and base and to the right of the hook scale.
- 12. Turn H1 infeed knob for desired carbide removal. The dial indicator H5 can be used to set the specific amount of material removal.
- 13. When the set up is complete, then select AUTO on joyswitch C-8.

PROGRAM ALTERNATE

This program is used for alternate face, or alternate top sharpening.

- 1. Set grind program C-3 on control panel to ALT.
- 2. Set back angle (hook angle if face sharpening) at hook switch C-9 on control panel.
- 3. Set # of teeth to be sharpened on tooth counter. C-7 on control panel.
- 4. Load saw. Use proper bushing located in tool drawer. Tool drawer is located under bottom row of adjustments, just under the control panel.
- 5. Use height sensor to set saw height. The height sensor arm is located above and behind the fixed clamp jaw. Rotate the arm so it is near the index finger. Then rotate the saw so the height sensor arm will rest on the tooth. Hold the joyswitch C-8 to in to move the saw up until the arm is lifted by the saw to the proper height (the saw lift will stop automatically). Now rotate the arm so it rests against pin behind height sensor arm. The saw is now at the proper height.
- 6. Set plate thickness C-11 to proper plate setting. Use micrometer to measure the thickness of the saw. Turn C-11 so that the numbers match the readings on the micrometer.



PROGRAM ALTERNATE (Continued)

- 7. Install desired bevel angle washer onto H6. Washers are located in tool drawer. Note that no washer is necessary for a 45° bevel.
- 8. Pull start button C-6 on control panel. Note that the coolant can be toggled on/off with the start button, while putting the joyswitch into automatic will always turn the coolant on.
- 9. Set index pitch. This is done by holding the joyswitch C-8 to index, while turning knob C-10 to the desired setting. Make sure that C-10 locks into position before releasing C-8 to the center position. This process may need to be repeated to fine tune the index system.
- 10. Index the set up tooth into position. This tooth must be right.
- 11. Turn the spindle motor on by using the joyswitch C-8 to the IN position. Adjust feed speed forward C-12 to desired speed. Use caution not to let the grinding wheel contact the carbide too hard. You can also adjust feed reverse C-13 at this time. Typically C-13 is adjusted fully open.
- 12. While adjusting feed speeds, the stroke length can also be set. When using a 6" top wheel select the 6" top stroke adjustment block. When using a 6" face wheel select the 6" face stroke adjustment block. When using wheel combination and a 4.5" top wheel select a 4.5" adjustment block. The stroke length can be adjusted by turning the knurled knobs on the selected block. This block is located between grind head and base and to the right of the hook scale.
- 13. Turn H1 infeed knob for desired carbide removal. The dial indicator H5 can be used to set the specific amount of material removal.
- 14. When face sharpening, a slight correction of the plate thickness C-11 may be necessary to achieve equal removal on left to right face bevels.
- 15. Stop by pushing C-6 then start by pulling C-6 until green light comes on. Move joy switch to INDEX to position right tooth.
- 16. Move the joy switch C-8 to IN to move grinding wheel across the carbide until lift off engages. Then move joy switch to OUT until the head stops. The grinding head should now bevel left.
- 17. Move joy switch C-8 to INDEX for the next tooth to be ground.
- 18. Move joy switch C-8 to IN to move grinding wheel across the carbide until lift off engages. Then move joy switch to OUT until head stops. The grinding head should now bevel right.



PROGRAM ALTERNATE (Continued)

20. If removal is even then place joy switch C-8 to AUTO.

PROGRAM CHAMFER

This program is used for the tops of chamfer teeth.

- 1. Set grind program C-3 on control panel to Chamfer.
- 2. Set back angle at hook switch C-9 on control panel.
- 3. Set # of teeth to be sharpened on tooth counter. C-7 on control panel.
- 4. Load saw. Use proper bushing located in tool drawer. Tool drawer is located under bottom row of adjustments, just under the control panel.
- 5. Use height sensor to set saw height. The height sensor arm is located above and behind the fixed clamp jaw. Rotate the arm so it is near the index finger. Then rotate the saw so the height sensor arm will rest on the tooth. Hold the joyswitch C-8 to in to move the saw up until the arm is lifted by the saw to the proper height (the saw lift will stop automatically). Now rotate the arm so it rests against pin behind height sensor arm. The saw is now at the proper height.
- 6. Set plate thickness C-11 to proper plate setting. Use micrometer to measure the thickness of the saw. Turn C-11 so that the numbers match the readings on the micrometer.
- 7. Install desired bevel angle washer onto H6. Washers are located in tool drawer. Note that no washer is necessary for a 45° bevel.
- 8. Pull start button C-6 on control panel. Note that the coolant can be toggled on/off with the start button, while putting the joyswitch into automatic will always turn the coolant on.
- 9. Set index pitch. This is done by holding the joyswitch C-8 to index, while turning knob C-10 to the desired setting. Make sure that C-10 locks into position before releasing C-8 to the center position. This process may need to be repeated to fine tune the index system.
- 10. Index the set up tooth into position.
- 11. Turn the spindle motor on by briefly jogging the joyswitch C-8 to the IN position. Adjust feed speed forward C-12 to desired speed. Use caution not to let the grinding wheel contact the carbide. You can also adjust feed reverse C-13 at this time. Typically C-13 is adjusted fully open.





PROGRAM CHAMFER (Continued)


- 12. While adjusting feed speeds, the stroke length can also be set. When using a 6" top wheel select the 6" top stroke adjustment block. When using a 6" face wheel select the 6" face stroke adjustment block. When using wheel combination and a 4.5" top wheel select a 4.5" adjustment block. The stroke length can be adjusted by turning the knurled knobs on the selected block. This block is located between grind head and base and to the right of the hook scale.
- 13. Turn H-1 infeed knob for desired carbide removal, using dial indicator H-5 for monitoring the amount of removal.
- 14. Move the joyswitch C-8 to IN to move the grinding wheel across the carbide until lift off engages. Then move joyswitch to OUT until head stops. Head should now bevel right. Use H-3 on lift off assembly to adjust the amount of chamfer by briefly jogging the joyswitch to IN while turning the H-3 ring. Continue this until the H-3 is adjusted to the desired amount. After H-3 is adjusted, hold the joyswitch to IN until the grinding head lifts off, then move the joyswitch to OUT.
- 15. Head should now bevel left. Check to see that carbide removal matches on left and right bevels. This is done by inspecting the tooth that you just ground.
- 16. If removal is even, place joy switch C-8 to AUTO.

Note: **HI-LOW** program is available only as an option.






AIR SCHEMATIC (SHEET 1)







AIR SCHEMATIC (SHEET 2)








ADJUSTING AIR PRESSURE SWITCH (A-5785)

When air pressure to the machine falls below normal limits (80 P.S.I.), the machine cycle will lock up. The air pressure switch may be adjusted to compensate for low air pressure only if the maximum pressure does <u>NOT</u> exceed 80 P.S.I.. Call Wright Machine Tool if you have any questions or are in need for further details.




- 1. Turn nut 1 down to raise low operating point.
- 2. Turn nut 2 down to raise high operating point.


CAUTION: TO AVOID DAMAGE DO NOT EXCEED THE MAXIMUM ALLOWABLE PRESSURE. CHECK SWITCH OPERATION AFTER RESETTING.



PLC WIRING SCHEMETIC TALON T/F




OUTPUT PANEL WIRING SCHEMATIC








"C" CARD SCHEMATIC








"D" CARD SCHEMATIC








"E" CARD SCHEMATIC








"F" CARD SCHEMATIC








"G" CARD SCHEMATIC






POWER PANEL









ELECTRICAL SCHEMATICS





























NOTE: DISCONNECT POWER FIRST! CONVERTING 230V TO 440V

WIRING CHANGE FOR MOTOR

WHITE

LINE 1 LINE 2

RED

LINE 3

BLACK

SET MOTOR STARTER
OVERLOAD AT 3.2


JUMP TOGETHER

6 & 9

5 & 8

4 & 7

TRANSFORMER



TAKE JUMPER OFF H-1 AND H-3 AND OFF H-2 AND H-4, SO THE RED AND BLACK WIRE ARE THE ONLY WIRES IN CONNECTION. CONNECT A JUMPER BETWEEN H-2 AND H-3. PUT THE 440 STICKER OVER THE 240 ON THE ELECTRICAL NAME PLATE.





PARTS LIST


DRAWINGS OF...

Base Layout Control Panel Assembly Index Arm Assembly Index Cylinder Assembly **Index Adjustment Assembly** Speed Control Assembly **Hook Actuator Assembly** Stroke Assembly Plate Thickness Knob Assembly Plate Thickness Sprocket Assembly Feed System Assembly Alternate Assembly **Counter Balance Assembly** Lift Off Cylinder Stack Assembly (H-3) **Head Assembly** Saw Clamp Assembly Sawlift Assembly






BASE ASSEMBLY LAYOUT





CONTROL PANEL COMPONENTS










CONTROL PANEL COMPONENTS CONTINUED

4 POSITION SELECTOR SWITCH - W-1003-GE





COUNTER COMPLETE - W-195 COVER ONLY - W-195-1





EMERGENCY STOP (PANIC BUTTON) - A-5680












CONTROL PANEL COMPONENTS CONTINUED


PUSH / PULL: START / STOP BUTTON - W-194-GE







TOTALIZER - W-70





JOY SWITCH - W-735-GE












CONTROL PANEL COMPONENTS CONTINUED

HOOK SWITCH - A-5690-GE






INDEX ARM ASSEMBLY






INDEX CYLINDER ASSEMBLY








INDEX ADJUSTMENT ASSEMBLY






SPEED CONTROL ASSEMBLY







HOOK ACTUATOR ASSEMBLY



STROKE ASSEMBLY








PLATE THICKNESS KNOB ASSEMBLY










PLATE THICKNESS SPROCKET ASSEMBLY








FEED SYSTEM ASSEMBLY








PIVOT ASSEMBLY








COUNTER BALANCE ASSEMBLY




COUNTER BALANCE CYLINDER ASSEMBLY






LIFT OFF CYLINDER STACK ASSEMBLY (H-3)








HEAD ASSEMBLY






SAW CLAMP ASSEMBLY








SAWLIFT ASSEMBLY



NOTE: DISCONNECT POWER FIRST! MOTOR REPLACEMENT INSTRUCTIONS





NOTE:

RUN MACHINE IN ALTERNATE. IF THE BELT SQUEALS WHEN REVERSING THEN TIGHTEN BELT. IF LIFT OFF DOES NOT FUNCTION THEN LOOSEN BELT BY ADJUSTING THE MOTOR.



NOTE: DISCONNECT POWER FIRST! BELT REPLACEMENT INSTRUCTIONS






NOTE:
RUN MACHINE IN ALTERNATE. IF THE BELT
SQUEALS WHEN REVERSING THEN TIGHTEN BELT.
IF LIFT OFF DOES NOT FUNCTION THEN LOOSEN
BELT BY ADJUSTING THE MOTOR.




NOTE: DISCONNECT POWER FIRST! SPINDLE REPLACEMENT INSTRUCTIONS








NOTE: DISCONNECT POWER FIRST! SPINDLE REPLACEMENT INSTRUCTIONS CONTINUED



INSTALL THE NEW SPINDLE IN THE SAME MANNER AS SHOWN IN STEPS 1-10. BE SURE THE BELT LINES UP IN BELT GROOVES ON THE MOTOR AND SPINDLE PULLEYS.



NOTE: ON THE WHEEL COVER SET SCREW - JUST RUNNING IT UP SNUG IS ALL THAT IS NEEDED.
OVERTIGHTENED SET SCREW WILL HARM SPINDLE.
ON LATER MACHINES THE SET SCREW WAS REPLACED BY A SPLIT GUARD AND SOCKET HEAD CAP SCREW.
THE NEW STYLE SHOULD ONLY BE SNUG AND NOT OVERTIGHTENED.



Index

Symbols

1/4 TEE HANDLE KEY 7 13 PC. ALLEN WRENCH SET 7 3 PIN SAW CENTER 7

Α

ACCESSORIES 7
ADJUSTING AIR PRESSURE SWITCH 31
AIR PRESSURE 9, 14
AIR REQUIREMENTS 5
AIR SCHEMATIC 29, 30
AIR SUPPLY 9
ALLEN WRENCH SET 7
ALTERNATE ASSEMBLY 61
ALTERNATIOS ANGLE WASHERS 7

В

BASE ASSEMBLY LAYOUT 47
BELT REPLACEMENT INSTRUCTIONS 69
BEVEL ANGLE ADJUSTMENT 16

C

CENTRAL LUBRICATOR SYSTEM 19
CIRCUIT SIZE 5
COMMON REPLACEMENT PARTS 7
CONTROL PANEL 10, 11, 12
CONTROL PANEL COMPONENTS 48, 49, 50, 51
CONVERTING 230V TO 440V 45
COOLANT FILTERS 7
COOLANT SAFETY 3
COUNTER BALANCE ASSEMBLY 62
COUNTER BALANCE CYLINDER 63
CYCLE TIME 21

F

EAR PROTECTION 4
ELECTRICAL DISCONNECT 12
ELECTRICAL SCHEMATICS 40
EMERGENCY STOP 11
EYE PROTECTION 4





F

FACE 25 FACE WHEEL 7 FEATURES 6 FEED FINGER 7 FEED RAMP 7 FEED RATE 21 FEED SPEED ADJUSTMENTS 12 FEED SYSTEM 60 FILTER PAPER 7 FILTER REPLACEMENT 20 FINGER ARM PIVOT BEARING 7 FINGER ARM SPRING 7 FINGER BOSS 7 FINGER SPRING 7 FIXED CLAMP JAW 7 FLAT FACES 22 FLAT TOPS 22

G

GENERAL SAFETY RULES 4, 5 GRIND SPEED 21 GRINDING HEIGHT ADJUSTMENTS 16 GRINDING WHEELS 8

Н

HEAD ASSEMBLY 65 HOOK 11 HOOK ACTUATOR 56

ı

INDEX ADJUSTMENT 54 INDEX ARM ASSEMBLY 52 INDEX CYLINDER 53 INDEX PITCH 11 INDICATOR 16

J

JOY SWITCH 11

L

LARGE BORE OPTION 7 LIFT OFF CYLINDER 64 LIMITED WARRANTY 2





M

MACHINE INSTALLATION 8
MACHINE SIZE 5
MACHINE WEIGHT 5
MAGNETIC SAW RECEIVER 7
MAINTENANCE 18, 20
MONITOR LIGHT 12
MOTOR REPLACEMENT 20, 68
MOTOR REPLACEMENT INSTRUCTIONS 68
MOUNTING GRINDING WHEELS 8

0

OPTIONAL VOLTAGE 5 OPTIONS 7 OUTPUT PANEL 33

P

PARTS LIST 46
PLATE THICKNESS 12
PLATE THICKNESS KNOB 58
PLATE THICKNESS SPROCKET 59
POWER PANEL 39
PRE SET UP COOLANT 8
PRECAUTIONS 4
PROGRAM SELECTOR 11

R

RAMP FOLLOWER 7
RECOMMENDED FLOOR SPACE 8
RELOAD CHECK LIST 13
REPLACEMENT PARTS 7
RUST DAMAGE 8
RUST INHIBITING 8

S

SAFETY PROCEDURES 4
SAFETY RULES 4, 5
SAW BUSHING SIZES 7
SAW CENTER WASHER 7
SAW CLAMP 66
SAWLIFT 67
SET UP COOLANT 8
SETUP 14, 15
SETUP CHECKLIST 13
SHIPPING WEIGHT 5





SPECIFICATIONS 5
SPEED CONTROL 55
SPINDLE MOTOR 5
SPINDLE REPLACEMENT INSTRUCTIONS 70, 71
SPLINE BORE SAW CENTER 7
STANDARD ACCESSORIES 7
STANDARD SAW SIZE 5
STANDARD VOLTAGE 5
START / STOP 11
STROKE ASSEMBLY 57

T

TEE HANDLE KEY 7
TEETH PER 21
THINGS TO CHECK IF PROBLEMS EXIST 17
TOOTH COUNTER 11
TOP 25
TOP WHEEL 7
TOTALIZER 11

W

WARRANTY 2
WHEEL POSITION STOPS 7



